

U.S. Department of Transportation

National Highway Traffic Safety Administration

October 14, 2015

Mr. Thomas Olson
Product Compliance Manager
Winnebago Industries, Inc
605 West Crystal Lake Road

NVS-215MR
15V-625

1200 New Jersey Avenue SE Washington, DC 20590

Subject: LP Hose Hardening may Result in LP Leak

Dear Mr. Olson:

P.O. Box 152 Forest City, IA 50436

This letter serves to acknowledge Winnebago Industries, Inc's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ITASCA/ELIPSE/2013-2016
ITASCA/MERIDIAN/2013-2016
ITASCA/NAVION/2013-2016
ITASCA/REYO/2013-2016
ITASCA/VIVA/2013-2016
WINNEBAGO/ERA/2013-2016
WINNEBAGO/JOURNEY/2013-2016
WINNEBAGO/TOUR/2013-2016
WINNEBAGO/TRAVATO/2013-2016
WINNEBAGO/TREND/2013-2016
WINNEBAGO/VIA/2013-2016
WINNEBAGO/VIEW/2013-2016

Mfr's Report Date: October 2, 2015

NHTSA Campaign Number: 15V-625

Components:

EQUIPMENT: RECREATIONAL VEHICLE: LPG SYSTEMS

Potential Number of Units Affected: 8,842

Problem Description:

Winnebago Industries, Inc. (Winnebago) is recalling certain model year 2013-2016 Winnebago Era, Travato, View, Trend, Via, Journey, and Tour motorhomes and Itasca Navion, Viva, Reyo, Meridian, and Elipse motorhomes manufactured June 26, 2012, to August 26, 2015. In the affected vehicles, the high pressure liquid propane (LP) hose may harden and result in an LP leak at the crimp fitting.

Consequence:

An LP leak in the presence of an ignition source increases the risk of a fire.



Remedy:

Winnebago will notify owners, and dealers will replace the LP hose, free of charge. Remedy parts are not currently available. The manufacturer has not yet provided a notification schedule. Owners may contact Winnebago customer service at 1-641-585-3535.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at 202-366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division

Office of Defects Investigations

Enforcement

